

COAL FIRED BOILER - PRINCIPALS

Executive Talk : Coal Fired Boiler - Principles Funded by : Akaun Amanah Industri Bekalan Elektrik (AAIBE)





Presented by: Bernard Anderson Principal Process Design Engineer HRL Technology Pty Ltd.



Presentation Outline

- 1. Coal Fired Power Plant Basics
- 2. Origin and Properties of Coal
- 3. Influence of Coal Properties on Boiler Operation
- 4. Effect of Steam Cycle Conditions on Efficiency
- 5. Problems that can be Caused by Coal in Boilers
- 6. Examples of Power Plant Problems Caused by Coal

The energy experts The



POWER PLANT BOILER


- Produce steam of the specified quality at the desired production rate.
- Contain the combustion process to facilitate heat transfer from the flames and hot gases to the water and steam tubes.


 Facilitate stable combustion conditions for the coal.





POWER PLANT OPERATING SYSTEMS

Water/Steam
Coal/Air/Flue Gas
Ash











Power Station Videos


- ...Videos\Coal Fired Power Plant.mp4
- ...Videos\How a thermal power plant works.mp4



Power Plant Overview

Plant gross power	744992	КW
Plant net power	701303	kW
Number of units	1	
Plant net HR (HHV)	10235	kJ/kWh
Plant net HR (LHV)	9632	kJ/kWh
Plant net eff (HHV)	35.17	%
Plant net eff (LHV)	37.37	%
Aux & losses	43689	kW
Fuel heat input (HHV)	1993778	kJ/s
Fuel heat input (LHV)	1876453	kJ/s
Fuel flow '```	7902	t/day







STEAM PRO 25.0 Bernie HRL Technology Pty Ltd. 485 10-16-2015 20:51:13 C:\Andeb\IFME\Boiler Training\TFlow\TBP 700 MW Unit, Ver 1.STP



Boiler Details








Typical 700 MW

p [bar] T [C] h [kJ/kg] M [kg/s] x [-]

STEAM PRO 25.0 HRL Limited HRL Technology Pty Ltd.
 485 10-19-2015 10:02:34 C:\Andeb\IFME\Boiler Training\TFlow\TBP 700 MW Unit, Ver 1.STP




Rankine Cycle with Reheat




T-s Diagram of Rankine Cycle with Reheat

HRLTechnology 🚳 HRL.

Turbine Details







Typical 700 MW


STEAMPRO 25.0 Bernie HRL Technology Pty Ltd.

485 10-16-2015 20:51:13 C:\Andeb\IFME\Boiler Training\TFlow\TBP 700 MW Unit, Ver 1.STP

p [bar] T [C] h [kJ/kg] M [kg/s] x [-]



Double HP Feed Water Heater Train & Single LP Feed Water Heater Train




Typical 700 MW

p [bar] T [C] h [kJ/kg] M [kg/s] Q [kJ/s] x [-]

STEAM PRO 25.0 HRL Limited HRL Technology Pty Ltd. 485 10-19-2015 10:02:34 C:\Andeb\IFME\Boiler Training\TFlow\TBP 700 MW Unit, Ver 1.STP




Unit Energy Outputs






Unit Auxiliaries and Losses







BOILER UNDER CONSTRUCTION






POWER PLANT BOILER

Main types of firing arrangements:

• Swirl burners - opposed and single wall fired.

• Slot burners - corner fired.





Coal Formation and Mining Videos

- ...Videos\The Formation of Coal 3D.mp4
- ...Videos\How Its Made Coal.mp4
- <u>..\Videos\PT Adimitra Baratama Nusantara.mp4</u> (2:30)



- Initially Malaysia's coal fired power stations only used Bituminous coals.
- Increasing cost has lead to increasing use of lower rank coals which are cheaper and readily available.
- Existing coal fired boilers can co-fire various grades of sub-bituminous coals.
- Manjung 4 and TBP 4 designed for 100% lower grade sub-bituminous coals.


The energy experts The en





Manjung 4 Specifications

MANJUNG 4 – TECHNICAL SPECIFICATIONS


TECHNICAL DATA OF STEAM GENERATOR	GUARANTEE		MODE OF OPERATION	
Main steam flow	3226 metric tons/hr 7111 M Lb/hr 282 barg 4090 psig 600 °C / 605 °C 1112 °F/1121 °F		• Sliding pressure operation with daily load swings from 30% to 100%	
Superheater outlet steam pressure				
Superheat/reheat steam temperature				
FUEL (AS RECEIVED)	DESIGN	RANGE	AIR HEATER	
Gross calorific value (kcal/kg) (Btu/Lb)	5200 9360	4500 – 5500 8100 – 9900	 2x trisector semi-modular Regenerative air heaters 	
Moisture content (%wt)	22.1%	8%-30%	AIR AND FLUE GAS SYSTEMS	
Ash content (%wt)	1.6%	1.5% - 13.9% 1.1% - 15%	 2x 50% primary air fans 2x 50% induced draft fans 2x 50% forced air draft fans 	
Sulphur (%wt)	0.47%	0.1% - 0.94%	GRINDING AND FIRING PLANT	
Volatile matter (%wt)	35%	22% – 45%	 8 gravimetric raw coal feeders 8 HP 1023 pulverisers with dynamic classifiers 	
Fixed carbon (%wt)	41%	35% - 58.1%		
FLUE GAS EMISSION LEVELS AT STACK	MG / NM3 @ 6%02		LB/ MMBTU	
Sulfur dioxide (SO2)	500		0.41	
Nitrogen oxides (NOx)	500		0.41	
Carbon monoxide (CO)	200		0.16	











Peat


HRL Technology MRL.

"humification"¹ – oxidation of plant matter and attack by aeorobic organisms (bacteria, fungi, insects). Hydrocarbons given off, remaining plant tissue higher in oxygen and carbon.

% Carbon = 60% daf % Volatile matter >60% SE (gross) MJ/Kg = 15 Vitrinite Reflect.(max) = 0.2%




Coal Formation





Coal Formation




rgy experts

The energy experts

Coal Formation

HRL Technology MRL.



... and so on, until anthracite is produced



Coal Rank

The Coalification Process.

With increasing pressure, temperature and time

	Composition Wt % (daf)			
	CARBON	HYDROGEN	OXYGEN	
WOOD	49	7	44	
PEAT	60	6	34	
LIGNITE	70	5	25	
SUB-BITUMINOUS	75	5	20	
BITUMINOUS	85	5	10	
ANTHRACITE	94	3	3	



HRLTechnology (MRL.

Effects of Coal Rank on a Boiler Low Rank Coal Compared to Higher Rank Coal

- Lower Heating value more coal, more air and more fluegas – ID Fan capacity limit.
- Higher moisture content more fluegas.
- More mill primary air required.
- Easier to mill better combustion
- Higher volatiles better combustion
- Increased SH and RH steam temperatures.
- Can have higher alkali in ash sintered ash deposits in superheater and reheater sections.
- Usually good ESP performance.



Effects of Coal Rank on a Boiler Low Rank Coal Compared to Higher Rank Coal

- Can have alkali elements directly attached to coal molecules rather than in the ash minerals such as clay, silica, alumina.
- As a result the ash can have a high content of reactive sodium, potassium, calcium, iron and magnesium.
- These elements can cause slagging in the furnace and solidification of sintered deposits on the SH and RH tubes.
- Behaviour of the ash can be more variable and less predictable than for higher rank coal.
- Difficult to eliminate the problem with tighter coal specifications.

The energy experts The energy



PLANT PERFORMANCE

Behaviour is affected by:

- Coal Properties
- Plant Design
- Method/Pattern of Operation

The energy experts The energy experts HRLTechnology Streets

Power Plant Performance Influence of Coal Properties

• Thermal Efficiency

- Availability
- Capacity
- Turn Down Capability
- Environmental



Influence of Coal Properties

Thermal Efficiency

- Carbon in Ash
- Moisture in Coal
- Heat in Flue Gas
- Excess Air / Air Heater Leakage



Influence of Coal Properties

Availability
Slagging
Fouling
Erosion



Influence of Coal Properties

- Capacity
- Coal Pulverising Limitation
 - Throughput
 - Mill outlet temperature
- Deposit Formation
- Emissions
 - NOx
 - Particulate



Influence of Coal Properties

Boiler Turn Down CapabilityCoal IgnitabilityFineness of Coal Grind

The energy experts The


HRL Technology 🚳 HRL.

Influence of Coal Properties

nergy experts


Environmental

- Particulates
- NOx
- SOx
- CO2
- Ash Storage




HRL Technology MRL.

The energy experts The energy experts HRLTechnology Stress









Volatile Matter

- Rapid Release & Combustion (50 milliseconds)
- Quantity of VM may be much higher than the Proximate VM
- Quantity influenced by:
- temperature (1500 °C)
- heating rate (10⁵ °C/s)



High VM gives High Combustion Reactivity:

- Rapid combustion helps ignition
- Less char remaining
- Char more reactive



Char remaining after devolatilisation

- Relatively slow combustion (some remaining after 3 seconds)
- Size, porosity, density, chemical reactivity all important
- Mix of particle types



PREDICTION

OF A COAL'S

PERFORMANCE



Testing at Different Scales

Standard Laboratory Analysis

Proximate, Ultimate, HGI etc

• Bench & Pilot-Scale

Attempt to simulate power plant processes better

• Full-scale trial burns



Stages & Scales of Coal Evaluation

	Lab. Analysis	Bench Scale Tests	Pilot Scale Tests	Power Station Tests
Precision				
Accurate Simulation				
Cost				-
Sample Requirements				_
Initial Resource	f			
Assessment	U			
Geological Mapping	÷	÷		
for Coal Quality	ŭ			
Pre-Treatment &	÷	÷	÷	
Washability Studies	-	-		
Trial Pit	÷	÷	÷	÷
Commercial Mining & Preparation	ţ	÷	÷	Ŷ

The energy experts The energy

HRLTechnology 🚳 HRL

Standard Laboratory Analysis

- Wide recognition
- Most suitable for contractual coal specifications
- Provides data in coal variability
- Helps to identify features of a coal that may need pilot-scale evaluation

But

Simulation of real processes may be poor

HRL Technology ShrL.

PULVERISING MILLS

erav experts


The energy experts The

 Pulverise coal (typically to 70% < 75 um, or finer).

• Dry the coal to assist with grinding, transport and combustion.

Convey the pulverised coal to the boiler.








PULVERISING MILLS

Three main types:

Slow speed - ball mills


• Medium speed - vertical spindle mills

• High speed - impact/attrition mills





Vertical Spindle Mill (CE Raymond Bowl Mill)



Balance of:


- Abrasion
 Resistance
- Power
 Consumption
- Dynamic Response

The energy experts The

HRL Technology (MRL.

High Speed Attritor Mill

energy experts



- Low Power Consumption
- Good Dynamic Response

The energy experts Th



PULVERISING MILLS


Potential performance issues:

- Capacity problems because coal is too difficult to grind.
- Capacity problems because coal has low energy content.
- PF fineness problems.
- Mill temperature problems which could lead to capacity problems or mill fires.
- High maintenance requirements because of abrasive nature of mineral matter in the coal.

HRL Technology 🚳 HRL.

and the second se		_
Milling/Pulverising		
Relevant Coal Quality	Comments	
Parameters		
Hardgrove Grindability	Power consumption,	
Index (HGI)	fineness	
Calorific Value	Required throughput	
Maistura Contant		
Moisture Content	Air temperature,	
Ash Content	spon. comb. Abrasiveness	
ASIT COILLEIL	ADIASIVEILESS	
Abrasion Index (YGP)	Abrasiveness	
Abrasion Index (TOF)	/ brasiveness	
Mineral composition	Abrasiveness	
(particularly free quartz		
and pyrite levels)		





HRL Technology 🚳 HRL.

The energy experts The energy expe

EFFECTIVENESS OF COMBUSTION REACTION

(Production of Heat from Coal Organic Matter)


1. Flame Stability & Turndown Capability

2. Burnout Efficiency



FLAME STABILITY & TURN DOWN Require:

- Early, strong ignition
- Lack of pulsations
- Maintained at low loads



The energy experts The en



Flame Stability/Turndown

Relevant Coal Quality Parameters	Comments		
VM Content (FR)*	Rapid heat generation to heat incoming coal/air		
Moisture Content			
Specific Energy			
SE of VM	Not a standard test		
PF Fineness (HGI)			
* Fuel Ratio (FR) = FC/VM			



BURNOUT EFFICIENCY (a component of Boiler Efficiency)

Required in order that:

- Maximum fuel value be obtained from the coal
- Minimum carbon-in-ash (Ash Utilisation)



BURNOUT EFFICIENCY (%)

Combustibles Burnt
 Total Combustibles

The energy experts The




BOILER EFFICIENCY

erav experts

Unburnt Carbon Loss (<u>Burnout Efficiency</u>) Dry Flue Gas Loss Increases with increasing flue gas temperature Wet Flue Gas Loss Increases with increasing moisture content Hydrogen Loss Loss of Gross Calorific Value due to Hydrogen Other Losses (estimated 0.5 - 1.0%)








Burnout Efficiency

Relevant Coal Quality Parameters	Comments		
VM Content (FR)*	Related to char <u>quantity</u>		
Maceral Analysis	Related to char <u>quality</u>		
Vitrinite Reflectance	Related to char <u>quality</u>		
PF Fineness (HGI)			
* Fuel Ratio (FR) = FC/VM			








ASH DEPOSITION

Covers:

- Deposition on tubes in the furnace area
 SLAGGING
- Deposition in convective sections reheaters, economisers and air heaters - FOULING.









EFFECTS OF SLAGGING

The energy experts Th

- Interference with heat transfer balance too little in radiant section, too much in convective section
- High Furnace Exit Temperature (Superheater Metal Temperature)
- High Boiler Exit Temperature (Boiler) Efficiency)




EFFECTS OF SLAGGING

- Lumps in Bottom of Furnace (Damage, Blockages)
- Interference with Burner Flow Patterns
- Excessive Soot-Blowing (Steam Wastage, Erosion)



SLAG FORMATION



The energy experts The



EFFECTS OF FOULING

- High Boiler Exit Temperature (Boiler Efficiency)
- Low Steam Temperature
- Excessive Soot-Blowing (Steam Wastage, Erosion)
- Poor Gas Flow Distribution (Erosion)
- Air-Heater Performance (Blockages, Heat Transfer)



ASH DEPOSITION

Affected by:

- Coal Properties mineral composition, moisture.
- Firing Arrangement
- Operating pattern



Deposit Formation						
Relevant Coal	Comments					
Quality Parameters						
Ash Fusion	IDT, Spherical Temp.,					
Temperature	Hemispherical Temp.,					
	Flow Temp.					
Ash Analysis	Fe, Ca, Mg, Na, K					
Indices based on	Many & various					
Ash Analysis	ŕ					

The energy experts The



ASH DEPOSITION

Limitations of Laboratory Tests:

 AFT does not take account of selective deposition

nerav experts

- AFT does not take account of variations in combustion conditions related to coal rank
- Indices are not applicable to all coals. Most do not apply to southern hemisphere coals

The energy experts The energy



ASH DEPOSITION

Example of Problem with Common Slagging Index: Slagging Index = (Base/Acid) * Sulphur Guidelines: If S.I. < 0.6, then no problems If S.I. > 2.6, there will be problems But Australian Coals generally have S.I. values< 0.6 because they have low sulphur values. They can still cause slagging problems




ELECTROSTATIC PRECIPITATOR

Purpose is to:


 Remove particulate matter from flue gas to satisfy local statutory environmental regulations.


 This would normally require a collection efficiency of >99.5%.














ELECTROSTATIC PRECIPITATOR Collection Efficiency


Determined by:

- Electrical resistivity
- Ash chemistry
- Coal sulphur content
- Particle size distribution
- Cohesiveness of ash layer











SO_x FORMATION

Composed of:


- SO₂ (predominates in stack)
- SO₃ (predominates in atmosphere)

Negative Effect: • Acid Rain

Positive Effect:

 SO₃ may improve electrostatic precipitation








SO ₂ Formation						
Relevant Coal Quality Parameters	Comments					
Coal Sulphur Content	Strong predictor					
Ash Chemistry	SO ₂ absorbed by Ash					
Ash Content						



Fluegas Desulphurisation Unit

SWFGD Flow Circuit - One Unit (Engineering Design)



STEAMPRO 25.0 Bernie HRL Technology Pty Ltd. 485 10-16-2015 20:51:13 C:\Andeb\IFME\Boiler Training\TFlow\TBP 700 MW Unit, Ver 1.STP P[bar] T[C] M[kg/s] w*[wt% salinity]




NO_x FORMATION Composed of: • N20 • NO · NO2 Effects: Photochemical Smog Acid Rain

NO_x FORMATION

HRL Technology ShrL.

Formed From:


- Nitrogen in Coal (Main Source)
- Nitrogen in Combustion Air (Lesser Source)






NO _x Foi	rmation
Relevant Coal Quality Parameters	Comments
Coal Nitrogen Content	Major Source, but poor predictor
VM Content	Low NOx Combustion Systems
Moisture Content	Flame Temperature
Coal Rank, Organic Chemistry	Complex Reactions

HRLTechnology 🚳 HRL.







Fly Ash Disposal & Utilisation

- Choices:Disposal
 - Occupies Valuable Land
 - Impacts on Water Quality
- Utilisation
 - How to find enough Uses?

Fly Ash in Concrete

HRL Technology MRL.

Typical Requirements


- Carbon in Ash (maximum specified)
- SiO₂ + Al₂O₃ + Fe₂O₃ (mininimum specified)
- SO₃ (max)
- Available alkalis (max)
- Fineness (min)
- Strength of Concrete Test Piece (min)
- Water requirement (max)




Ash Disposal

- Principal issue is release of leachable trace elements into ground water and surface water
- Toxicity judged by comparison of leachate analysis with drinking water standards; if Concentration Index > 100, deemed to be Hazardous Waste










Levels of Trace Element Leaching

Depends on:

- Trace elements in coal, then in ash
- Nature of ash (size, degree of melting)
- Major elements & radicals in ash (Ca, Mg, Na, K, Cl, SO₄, CO₃, which may determine ph of the leaching water
- pH of water entering the disposal site





Review of Effect of Coal Properties

- Please provide answers to the following Questions for discussion.
- What will be the effect if the coal is to be used in one of the existing 700 MW units in Malaysia:
- 1. What will be the effect if the coal CV is 5000 kcal/kg as fired.
- 2. The coal moisture is 25% (as fired).
- 3. The coal ash is 18% (as fired).
- 4. The HGI is 38.
- 5. The oxygen is 16% (as fired)
- 6. The sulphur is 1.2% (as fired)
- 7. The sodium + potassium (oxides) in ash is 5%
- 8. The iron oxide in ash is 11%



Effect of Steam Cycle Conditions on Unit Performance

Type of Power Plant	MW Gross	MS Pressure, Mpa	MS Temperature °C	RH Temperature °C
700 MW Subcritical	745	16.4	538	538
700 MW Ultra Supercritical	737	28.0	600	605
1000 MW Ultra Supercritical	1053	28.0	600	605
1000 MW Advanced USC	1050	30.0	700	730
700 MW GT Combined Cycle	724	16.6	600	600



Effect of Steam Cycle Conditions on Unit Performance

Comparison of Power Plants				
Coal - Adaro 5200 kcal/kg at 1.8 \$US	/GJ HHV			
Natural Gas at 5.4 \$US/GJ HHV				
Type of Power Plant	Unit Efficiency % Net HHV	Approx Cost \$M USD	Relative Cost of Electrcity	CO2 kg/MWh gross
700 MW Subcritical	35.2	1220	100	911
700 MW Ultra Supercritical	39.9	1460	87.6	808
1000 MW Ultra Supercritical	40.1	1970	84.7	803
1000 MW Advanced USC	42.8	2230	86.6	756
700 MW GT Combined Cycle	54.4	487	95.4	330

КW


744992

Plant gross power

Effect of Steam Cycle Conditions on Unit Performance 700 MW Subcritical Plant

HRL Technology ShrL.

Ambient



t STEAMPRO 25.0 Bernie HRL Technology Pty Ltd.

485 10-16-2015 20:48:19 C:\Andeb\IFME\Boiler Training\TFlow\TBP 700 MW Unit, Ver 1.STP

The energy experts

HRL Technology SHRL.


Effect of Steam Cycle Conditions on Unit Performance 1000 MW Ultra Supercritical

Plant gross power Plant net power Number of units Plant net HR (HHV) Plant net HR (HHV) Plant net eff (HHV) Plant net eff (HHV) Aux & losses Fuel heat input (HHV) Fuel heat input (LHV) Fuel flow	1053431 KW 999841 KW 1 8951 kJ/KWh 8453 kJ/KWh 40.08 % 42.59 % 53590 KW 8980 GJ/h 8452 GJ/h 9886 t/day		Ambient 1.013 p 30 T 60% RH 23.82 T wet bulb
SWFGD SWFGD SQ2 remove eff = 95 % 134.8T ID Fan Fabric Filter Dust collec eff = 99.9	125 T 4238 M	T 4 p 606 4 T 2724 7.M	2.358 M 40.01 T 5639 M 30.01 T 95639 M
	311 299.2 2921.4	11 p = 299.2 T = 291.2 T = 258.5 T = 225.5 T = 193 T = 160.2 T = 130.9 T = 101.6 T = 72.3 T = 120.2 T = 100.2 T = 101.6 T = 72.3 T = 100.2 T = 1	HRHX 43.78 T 22.09 p 43.34 T 1881.9 M
# STEAMPRO 25	5.0 Bernie HRL Technology Pty Lta	Double HP Feed Water Heater Train & Single LP Feed Water Heater Train	p [bar] T [C] M [t/h] x [-]
U 0112 LUTI 10 2.	Service intel reenhology i ty Eu		

485 10-16-2015 20:52:06 C:\Andeb\IFME\Boiler Training\TFlow\USC 1000 MW Unit, Ver 1.STP



Effect of Steam Cycle Conditions on Unit Performance 700 MW Gas Turbine Combined Cycle



p [bar] T [C] M[t/h], Steam Properties: IAPWS-IF97 485 10-14-2015 14:52:13 file=C:\Andeb\IFVE\Boiler Training\TFlow\@E-9HA 02 CC 700 MW.GTP



WHAT CAN GO WRONG WITH A COAL FIRED BOILER?

Review of Problems that can be Caused by Coal Combustion in a Boiler.



- Sticky coal from surface water and/or clay can block conveyors and chutes.
- Fine coal can cause stockpile slumping following heavy rain.
- Wet Coal:
 - Low mill exit temperature.
 - Burner fuel duct blockages.
 - Reduced boiler efficiency.



- Contaminated coal large rocks or pieces of steel can damage conveyors and mills.
- High ash content:
 - Low CV
 - Excessive furnace ash.
 - High Fluegas dust emissions.
 - Reduced boiler efficiency.



- Low ash fusion temperature furnace wall slagging:
 - Reduced furnace heat transfer.
 - High furnace exit gas temperature.
 - Slag falls damage submerged chain conveyor and ash hopper walls.
 - Costly furnace cleaning.
 - Boiler tube damage.



- High Sulphur content:
 - High SO₂ emissions
 - Increased FGD operating costs.
 - Increased boiler back-end corrosion.
- Low sulphur content:
 - Possible poor ESP performance.
- High load operation increased furnace exit temperatures:
 - Increased furnace wall slagging.
 - Increased SH and RH tube fouling.



Problems with High Rank Coal

- Hard Coal (low HGI):
 - Difficult to mill.
 - Mill vibration and wear.
 - Coarse fuel to burners.
 - Excessive holdup of coal in mills boiler instability.
- Low volatile content:
 - Can cause slow ignition.
 - Flame instability
 - Loss of flame detection boiler trip.



Problems with High Rank Coal

- Slow burning low furnace heat transfer:
 - Excessive superheat temperatures.
 - High tube metal temperatures.
 - Reduced boiler efficiency or output.
- Slow burning high carbon in ash:
 - Flyash not acceptable for cement making.
 - Reduced boiler efficiency.



Problems with High Rank Coal

- High flame temperature:
 - Increased furnace heat transfer.
 - Furnace wall slagging.
 - Reduced steam temperatures.



- Self-heating and spontaneous combustion in stockpiles.
- Dust emissions from coal plant.
- Higher moisture content reduced boiler efficiency.
- Possible mill fires.



- Increased Fluegas flowrate:
 - ID fan capacity can limit boiler output.
 - ESP performance reduced higher dust emissions (worse with cofiring).
 - Higher SH and RH steam temperatures.
 - High SH and RH tube metal temperatures.



- High alkali in ash content:
 - Sintered deposits on superheater and reheater tubes.
 - Reduced heat transfer to SH and RH steam
 - Reduced SH and RH steam temperatures.
 - Reduced unit efficiency.
 - Turbine trip.
 - Excessive sootblowing required to remove deposits online.
 - Deposits can fall onto the economiser tubes and block the gas flow.
 - Costly boiler cleaning offline.




• Co-firing high rank coal with low rank coal can aggravate ash fouling from the low rank coal because of increased furnace exit temperature.





• Plant: Paiton, Units 1 & 2, 2 x 400 MW, Indonesia

- Excessive RH tube metal temperatures on one side of boiler.
- Coincided with increased use of low CV sub-bituminous coal.
- Boiler design coal CV 6000 kcal/kg, operating coal 4900 5200 kcal/kg.
- Higher boiler firing rates due to turbine wear
- Higher furnace exit gas temperatures.
- Boiler design (CE) with tangent firing causes higher gas velocity and higher gas temperatures on one side.
- Solution: shorten RH tubes on the hot side.











- Boiler Slagging and Fouling.
 - Plant: Suralaya, Units 5 & 6, Indonesia.
 - Suralaya Power Station Units 5 and 6 (2 x 600 MW) were affected by slagging and fouling whilst burning coal supplied by PT Berau. A number of outages were caused by slag falls which damaged the submerged chain conveyors and blocked the furnace ash hopper outlet.
 - Samples of slag from the boilers and samples of leftover Berau coal were taken and analysed.



- The chemical composition of the slag closely matched that of the coal sampled thus linking the coal sampled to the slagging problem. The sampled coal analysis was quite different to the Berau coal analyses done by both the power station and by Berau.
- The sampled coal ash contains very high levels of sodium (16.5 % Na2O in ash) which would be expected to cause severe slagging and fouling in boilers that run as hot as the Suralaya 600 MW units.
- It is believed that Berau were mining a coal seam which contained more sodium than previous seams.



- Furnace Slag Falls Damage Submerged Chain Conveyors.
 - Plant: Pagbilao, 2 x 380 MW, Philippines
 - Excessive furnace slagging resulting in slag falls which have damaged the submerged chain conveyors. Boilers shutdown for repairs.
 - The coal (Tanito) has a low ash fusion temperature (1200 1240°C IDT) although this is within the specification range for the coal supply contract.
 - The boilers are undersized for the design load resulting in high flame temperatures.



- There is evidence of high gas temperatures (1250 1300°C) close to the furnace walls which encourages slagging.
- The coal has a high iron and clay content in the ash which causes the low ash fusion temperatures.
- The boiler efficiency is reduced because of increased flue gas temperatures.
- Power station trying to avoid using the coal.



Stockpile Fires

- Low CV sub-bituminous coal is more reactive than higher rank black coal.
- Self-heating and spontaneous combustion of the coal in stockpiles is a common occurrence with low rank coals.
- Can take several weeks for spontaneous combustion to occur so need to use the coal quickly.
- Strong winds aggravate the problem by forcing more air through the stockpile.
- Burning coal can cause damage to conveyors and mill fires.
- The smoke can be bad for nearby villages leading to complaints.
- Careful stockpile management and compacting required to reduce the problem.



• Mill Fires

- Plant: Hong Kong Electric, Lamma Island, 250 & 350 MW units.
- Two mill fires occurred when burning Jembayan coal.
- No damage was caused to the plant by the mill fires. However the incidents resulted in a temporary load reduction on the unit and expense for inspecting the mill for damage and investigation of the cause of the fires.
- The Jembayan coal has a low rank makes it more reactive than higher ranked coals.
- Relative Ignition Temperature tests performed on the coal showed that the samples tested had significantly lower ignition temperatures than most other coals that had been tested.
- Solution: reduce the mill outlet temperature setting which reduces the drying and heating of the coal.



Ash Hopper Explosions

- Plant: Millmerran, Queensland, Australia,
- Ash falling into the furnace ash hopper water tank has caused steam explosions in the tank which has damaged the tank and tripped the furnace off-line due furnace pressure excursions.
- This problem is typically caused by large lumps or quantities of hot ash falling into the water tank and causing rapid steam production in the tank. This creates pressure waves in the water which can damage the tank and also pressure surges in the furnace which can trip the boiler offline.
- The explosions appear to be caused by weak friable deposits of ash falling from the furnace walls or superheater tubes that breakup rapidly when they hit the water.
- The solution requires the deposition to be reduced so that large deposits are not formed.



• Furnace Ash Hopper Filled with Solidified Slag

- Plant: Stanwell PS, Queensland, Australia, 4 x 365 MW.
- Unit 1 experienced a significant slagging episode during mid-March 2004. The episode led to the formation of clinker / slag on the furnace water walls of the boiler that extended halfway along the boiler hearth. This caused large lumps of clinker to bridge across the boiler hopper and then block the draglink conveyor. The Unit had to be shut-down for 8 days so that the major clinker / slagging formation could be removed and then the Unit returned to service.
- On the occasion of the furnace blockage the ash content of the coal was 17% instead of the usual 12% and also had higher iron content than normal. The ash was found to sinter at temperatures between 1150 and 1200°C



Fly-Ash Hopper Collapse

- Liddell PS, NSW Australia.
- Fabric Filter section collapsed. Unit offline for months for repairs.
- A high ash level alarm in a flyash hopper of a fabric filter was ignored. The ash was not being removed from the filter hopper and eventually the weight of the ash caused the entire filter to collapse.
- Better operator training required to avoid a repeat.



- Manjung PS, 3 x 700 MW plus 1 x 1000 MW
 - Boiler (700 MW unit) tripped offline following a slag fall when burning DEJ coal.
 - DEJ coal blamed for causing slagging boiler instability.
 - Investigation revealed that the slag was caused by the coal used before DEJ.
 - The Manjung 700 MW boilers had a design problem with poor stability of the water level in the steam drum. If level gets too high or too low the boiler and turbine will be tripped offline and can take some hours to get it back online.



- The DEJ coal was harder than other coals and difficult to mill. This caused an increased holdup of coal in the grinding mills which caused a slower response of the coal flow to the burners to changes in the coal feed rate into the mills.
- The slow response of the coal flow to the burners lead to increased instability in the boiler pressure and drum level controls. This lead to the boiler trip when it was disturbed by the slag fall.
- The boiler control system needed some retuning for the harder coal which had to be done by the OEM.



- Kapar Stage 3, 2 x 500 MW.
 - Problem occurred during a trial burn with Ensham Coal (Australian).
 When burning 100% Ensham coal at boiler loads above about 60% the main steam and reheat steam temperatures to the turbine would drop excessively. The normal steam temperature is around 538°C but it was dropping down as low as 410°C which was too low for the turbine and also caused a loss of efficiency.
 - The drop in steam temperature was being caused by too much heat transfer occurring in the furnace and not enough in the superheaters.



- The reason for the change in heat transfer was not clear and may have been caused by the ash properties or higher flame temperatures
- The Stage 3 boiler design was not suitable for the Ensham coal however the coal performed satisfactorily in the Kapar Stage 2 boilers.
- The Ensham coal only be used in Stage 3 boilers when co-fired with another coal



- Kapar Stage 2, 3 x 300 MW
 - Combustion trial with Bontang coal (Indonesian).
 - Bontang coal is a low rank coal with a good CV and low ash content but high sodium and potassium in the ash.
 - Boiler operation initially OK but after 4 days there were large ash deposits in the furnace and on the superheater tubes. Operation was able to continue with increased use of sootblowers to control the ash deposits.
 - After about 8 days on Bontang coal the furnace gas pressure started to increase despite the ID fan running at full capacity. The problem was caused by a thick layer of ash deposits on top of the economiser tubes.




- After 10 days the boiler was shut down with a tube leak adjacent to the economiser. This was probably caused by erosion of the wall tubes due to high gas velocities in the remaining gas flow path.
- The tube repairs were expensive and the boiler was offline for a few days.
- The ash deposition was due to the relatively high sodium and potassium content of the ash. This causes sintering of the ash deposits in superheater and reheater tube banks. When the deposits are blown off the tubes with sootblowers they fall down and can accumulate on the top of the economiser because of the closer tube spacing there.



• Tanjung Bin PS, 3 x 700 MW Units.

- Problem: High fluegas dust emissions being attributed to the use of Forzando (South African) coal.
- Several shipments of this coal have been successfully burnt at this power station except for a problem with elevated dust emissions from the electrostatic precipitators (ESP). Forzando coal does not cause this problem at other power stations.
- The ESPs on each unit TBP consist of four parallel flow paths each with four zones in series. It was apparent from the ESP high voltage (HV) power supply data that only the first zone of each flow path was operating with a normal voltage. The other three zones in each path were operating with voltages too low for good ESP operation. The low voltages were causing the high dust emissions.







- At the same time, examination of the HV data for the other two units at TBP which were operating on different coals showed the same pattern of low voltages on 3 out 4 zones for each flow path. Hence the problem was due to the ESP design, not the Forzando coal.
- A review of the historical data for the TBP ESP indicated that this problem was present most of the time except for a few days after a boiler and ESP clean. This suggested the problem was caused by a build-up of ash on the ESP plates which can take a few days to accumulate. This problem is caused by inadequate rapping of the plates. If the ash layer builds up too much a phenomenon called "back corona" occurs which reduces the HV voltage and the efficiency of the ESP.
- TBP have improved the ESP rapping and reduced the dust emissions enough to meet the emission limits.



• Tanjung Bin PS, 3 x 700 MW

- Problem: TBP have suffered from ash fouling, economiser tube bank blockages and reheater and superheater tube failures.
- There is some correlation between blockage of the economiser tube banks and use of Twistdraai (South African) coal in all three units at TBP but several other coals were also burnt at the same time.
- TBP had been operating at high load continuously for long periods which leads to high gas temperatures and increase ash deposit formation.
- The blockage of the economiser tube banks appears to cause problems with reheater and superheater tube failures.



- There is clear evidence that at least one of the TBP boilers is suffering from an imbalance in the fuel and air splits. This could cause or contribute to ash fouling and overheating of reheater tubes.
- Twistdraai coal does not appear to have an ash composition that would cause ash fouling but the Kayan sub-bituminous coal that was co-fired with it does have relatively high alkali in ash.
- The Twistdraai coal was burnt without problems at Manjung, Kapar and Jimah power stations. It has also been used extensively in other countries without fouling problems.



- The two-pass boiler design with finned tube economiser is not a good design for use with low rank coals which cause sintered deposits in the superheater and reheater tube banks. Deposits falling from these tube banks will fall onto the top of the economiser tubes and can't get though because of the tight fin spacing.
- It is important to avoid the use of low rank coals such as the Kayan coal, which has elevated levels of sodium and potassium, in a two-pass boiler with a finned tube economiser.



- End of Presentation
- Questions
- Discussion