

Headline	SESB cables damaged after being shot		
MediaTitle	New Sabah Times English (KK)		
Date	15 May 2013	Color	Black/white
Section	Home	Circulation	23,655
Page No	L-13	Readership	
Language	English	ArticleSize	113 cm ²
Journalist	N/A	AdValue	RM 219
Frequency	Daily	PR Value	RM 657



SESB cables damaged after being shot

KOTA KINABALU: Irresponsible action by individuals damaging electrical installations belonging to SESB at Kampung Pangas Ulu early morning on May 11 had caused power outage to 20 houses in the village.

A trace of gunshot was dis-

covered on the Aeriel Bundle Cable (ABC) on May 13.

According to the Senior General Manager (Asset Management) SESB, Ir. Ahmad Fuad Md Kasim, electricity supply was fully restored on May 13.

He added that SESB took

longer time to detect and restore the entire electricity supply due to poor weather condition and hazardous road which was unsafe for heavy duty vehicles.

Consumers are encouraged to call SESB hotline at 15454 or 088-515000 if their elec-

tricity supply has been cut-off. In addition, a Short Messaging Service (SMS) is also available where users only have to type SESBR <space> types of complaint and send to 33154.

All complaints will be dealt with immediate action.